

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 07/07/2022
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G811	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	(X3) DATE SURVEY COMPLETED 07/05/2022
NAME OF PROVIDER OR SUPPLIER RES-CARE INC			STREET ADDRESS, CITY, STATE, ZIP CODE 1306 S BLOOMINGTON STREET GREENCASTLE, IN 46135	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
E 000	Initial Comments An Emergency Preparedness Survey was conducted by the Indiana Department of Health in accordance with 42 CFR 483.475. Survey Date: 07/05/22 Facility Number: 013405 Provider Number: 15G811 AIM Number: 201267570 At this Emergency Preparedness survey, Res-Care Inc. was found not in compliance with Emergency Preparedness Requirements for Medicare and Medicaid Participating Providers and Suppliers, 42 CFR 483.475 The facility has 20 certified beds. All 20 beds are certified for Medicaid. At the time of the survey, the census was 21.	E 000		
K 000	Quality Review completed on 07/06/22 INITIAL COMMENTS A Life Safety Code and Preoccupancy survey was conducted by the Indiana Department of Health in accordance with 42 CFR 483.90(a). This Life Safety Code and Preoccupancy survey was for the addition of one bed in the room identified as Room #10 was conducted. This room measured approximately 16 feet by 16 feet (or 256 square feet in size) and had a separate bathroom attached to it. It had only one bed and one client in it before the addition of one bed and was surveyed to make sure it met Code requirements.	K 000		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 07/07/2022
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G811	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 07/05/2022
NAME OF PROVIDER OR SUPPLIER RES-CARE INC			STREET ADDRESS, CITY, STATE, ZIP CODE 1306 S BLOOMINGTON STREET GREENCASTLE, IN 46135		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 000	<p>Continued From page 1 Survey Date: 07/05/22</p> <p>Facility Number: 013405 Provider Number: 15G811 AIM Number: 201267570</p> <p>At this Life Safety Code and Preoccupancy Survey, Res Care Inc. was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.90(a), Life Safety from Fire and the 2012 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 33, Existing Residential Board and Care Occupancies and with 410 IAC 9, Community Residential Facilities for Persons with Developmental Disabilities.</p> <p>This one-story facility with a partial basement was fully sprinklered. The facility has a fire alarm system with hard wired smoke detection on all levels including client sleeping rooms, corridors, and common living areas. The facility has the capacity for 20 and had a census of 21 at the time of this survey. The attic space is protected with an automatic sprinkler system.</p> <p>Calculation of the Evacuation Difficulty Score (E-Score) using NFPA 101, Alternative Approaches to Life Safety, Chapter 6, rated the facility Prompt with an E-Score of 1.32.</p> <p>Quality Review completed on 07/06/22</p>	K 000			